

## Legend

- Monitoring Point A - G
- Trench Well 1, 3, 7, and 11
- Deep vapor Monitoring Points: 1 - 12
- Shallow Vapor Monitoring Points: 21-41
- Vapor Extraction Well
- NR Data Not Recorded
- Debris/Fill Footprint
- Methane Generating Waste Footprint
- Perimeter Fence
- Methane Extraction Trench

RESULTS ARE IN PARTS PER MILLION BY VOLUME (PPMV)

N




FIGURE 1

Site Layout  
& Last 4 Methane Readings

Week Beginning  
11 July 2011  
Manor View Dump Site  
Fort George G. Meade, MD



1114 Benfield Boulevard, Suite A  
Millsville, Maryland 21108  
Tel (410) 987-0032 Fax (410) 987-4392

PROJECT NO.

FILE NO.

FIGURE 1